



*Solving environment-related business problems worldwide*

[www.deltaenv.com](http://www.deltaenv.com)

27141 Aliso Creek Road • Suite 270  
Aliso Viejo, California 92656 USA

949.362.3077 800.477.7411  
Fax 949.362.0290

April 10, 2006

Dr. Steven Speer  
Orange County Health Care Agency  
Environmental Health Division  
1241 East Dyer Road, Suite 120  
Santa Ana, California 92705

Subject: Well Destruction Report  
ARCO Facility No. 0629  
13482 Brookhurst Street  
Garden Grove, California  
OCHCA Case No. 95UT62

Dear Dr. Speer:

Delta Environmental Consultants, Inc. (Delta), on behalf of Atlantic Richfield Company, has prepared this *Well Destruction Report* detailing the proper destruction of ten groundwater monitoring wells at ARCO Facility No. 629, (the Site, Figure 1) located at 13482 Brookhurst Street, in the City of Garden Grove, California. A *Remedial Action Completion Certificate*, dated November 17, 2005, was received from the Orange County Health Care Agency (OCHCA) confirming the completion of site investigation and remedial action at the Site. All groundwater monitoring wells were properly destroyed in order to complete closure granted by the OCHCA. A copy of the correspondence is included as Attachment A.

### WELL DESTRUCTION ACTIVITIES

On December 8 and 9, 2005, Delta was on-site to oversee the destruction of ten groundwater monitoring wells (MW-1 through MW-9 and MW-9d). A site map showing the locations of all wells is provided as Figure 2. Well construction details for all wells are provided in Table 1. Cascade Drilling, Inc. of Norwalk, California (License No. C57-71510) was contracted to provide the equipment and personnel required to conduct the field activities. Prior to initiating field activities, a well destruction permit was obtained from the OCHCA, and Underground Service Alert and the OCHCA were notified. In addition, an encroachment permit from the City of Garden Grove was obtained to facilitate lane closure for the destruction of wells MW-6 and MW-8, located in Trask Avenue.

Groundwater monitoring wells MW-1, MW-2, MW-3, MW-4, MW-5, MW-7, MW-9 and MW-9d were properly destroyed by over-drilling to terminal depth using ten-inch diameter hollow stem augers. The resultant

boreholes were backfilled with bentonite grout from terminal depth to approximately 1.5 feet bgs through the hollow-stem augers. The borehole was completed to the surface with concrete.

Due to health and safety concerns involved with working in Trask Avenue, Delta was unable to complete the destruction of wells MW-6 and MW-8 during the December 2005 well destruction activities. After updating the necessary traffic control plans and obtaining a revised encroachment permit from the City of Garden Grove, Delta returned to the Site on the evening of February 25, 2006 to properly destroy wells MW-6 and MW-8.

Off-site groundwater monitoring wells MW-6 and MW-8 were properly destroyed by pressure grouting. Bentonite grout was pumped under pressure into each well casing until each well filled with grout. The top five-feet of each well were over-drilled using ten-inch diameter hollow stem augers. The remaining annulus was backfilled with bentonite grout and completed to the surface with concrete.

### REMARK/SIGNATURES

The recommendations contained in this report represent Delta's professional opinions based upon the currently available information and are arrived at in accordance with currently acceptable professional standards. This report is based upon a specific scope of work requested by the client. The Contract between Delta and its client outlines the scope of work, and only those tasks specifically authorized by that contract or outlined in this report were performed. This report is intended only for the use of Delta's Client and anyone else specifically listed on this report. Delta will not and cannot be liable for unauthorized reliance by any other third party. Other than as contained in this paragraph, Delta makes no express or implied warranty as to the contents of this report.

If you have any questions or comments concerning this report, please contact Bobby Lu at (714) 228-6783.

Sincerely,


**DELTA ENVIRONMENTAL CONSULTANTS, INC.**



Christopher A. Ota  
Project Manager




Bryan Van Wagner  
California Professional Geologist No. 5820  
California Hydrogeologist No. 295



Attachments: Figure 1 Site Location Map  
Figure 2 Site Map  
Table 1 Well Construction Details  
Attachment A OCHCA Correspondence dated November 17, 2005

cc: Mr. Bobby Lu, Atlantic Richfield Company, La Palma, California  
Mr. Dan Yokayama, OCHCA, Santa Ana, California  
Ms. Valerie Jahn-Bull, CRWQCB- Santa Ana Region, California



GENERAL NOTES:  
 BASE MAP FROM U.S.G.S.  
 ANAHEIM, CA. QUADRANGLE  
 7.5 MINUTE TOPOGRAPHIC MAP  
 1965  
 PHOTOREVISED 1981



QUADRANGLE LOCATION




FIGURE 1  
 SITE LOCATION MAP  
 ARCO FACILITY NO. 629  
 13482 BROOKHURST STREET  
 GARDEN GROVE, CA.

PROJECT NO.  
 AM00-622

DRAWN BY

FILE NO.  
 5-607-67Q

PREPARED BY  
 P. MANNS

DATE  
 03 JUL 02

REV.  
 1

REVIEWED BY



**Delta**  
 Environmental  
 Consultants, Inc.

TABLE 1

**WELL CONSTRUCTION DETAILS**  
**ARCO FACILITY NO. 629**  
**13482 BROOKHURST STREET**  
**GARDEN GROVE, CALIFORNIA**

Well I.D.	Date Construction Completed	Well Type	Total Depth (feet bgs)	Screen Interval (feet bgs)	Casing Diameter (inches)
MW-1	09/22/95	Groundwater	26.5	5 - 26.5	4
MW-2	01/24/96	Groundwater	26	6 - 26	4
MW-3	01/24/96	Groundwater	26	6 - 26	4
MW-4	01/24/96	Groundwater	26	6 - 26	4
MW-5	01/24/96	Groundwater	26	6 - 26	4
MW-6	12/10/96	Groundwater	27	7 - 27	4
MW-7	07/27/00	Groundwater	25	5 - 25	4
MW-8	07/27/00	Groundwater	25	5 - 25	4
MW-9	10/22/03	Groundwater	25	5 - 25	4
MW-9d	03/09/04	Groundwater	43	38-43	4

## NOTES:

bgs                      = Below ground surface

**ATTACHMENT A**  
OCHCA Correspondence dated November 17, 2005



**COUNTY OF ORANGE  
HEALTH CARE AGENCY**

**REGULATORY HEALTH SERVICES  
ENVIRONMENTAL HEALTH**



**NOV 22 2005**

**JULIETTE A. POULSON, RN, MN  
DIRECTOR**

**DAVID L. RILEY  
ASSISTANT DIRECTOR**

**MIKE SPURGEON  
DEPUTY AGENCY DIRECTOR  
REGULATORY HEALTH SERVICES**

**STEVEN K. WONG, REHS, MPH  
DIRECTOR  
ENVIRONMENTAL HEALTH**

**MAILING ADDRESS:  
1241 E. DYER RD., SUITE 120  
SANTA ANA, CA 92705-5811**

**TELEPHONE: (714) 433-8000  
FAX: (714) 754-1788  
E-MAIL: shealth@cochca.com**

November 17, 2005

Darrell Fah  
ARCO Products Company  
P.O. Box 5077  
Buena Park, CA 90622-5077

**Subject: Remedial Action Completion Certification**

**Re: Underground Storage Tank (UST) Case  
ARCO Facility #0629  
13482 Brookhurst Street  
Garden Grove, CA  
OCHCA Case No. 95UT62**

Dear Mr. Fah:

This letter confirms the completion of site investigation and corrective action for the underground storage tank(s) formerly located at the above-described location. Thank you for your cooperation throughout this investigation. Your willingness and promptness in responding to our inquiries concerning the former underground storage tank(s) are greatly appreciated.

Based on information in the above-referenced file and with the provision that the information provided to this Agency was accurate and representative of site conditions, this Agency finds that the site investigation and corrective action carried out at your underground storage tank(s) site is in compliance with the requirements of subdivisions (a) and (b) of Section 25296.10 of the Health and Safety Code and with corrective action regulations adopted pursuant to Section 25299.3 of the Health and Safety Code and that no further action related to the petroleum release(s) at the site is required.

This notice is issued pursuant to subdivision (h) of Section 25296.10 of the Health and Safety Code.

Please contact Steven Speer of our office at (714) 433-6255 if you have any questions regarding this matter.

Sincerely,


  
Steven K. Wong, REHS, MPH, Director  
Environmental Health

Attachment: Case Closure Summary

cc: Valerie Jahn-Bull, Santa Ana Regional Water Quality Control Board  
SB 562 Database, State Water Resources Control Board  
Cleanup Fund Manager, State Water Resources Control Board  
Larry Honeybourne, Environmental Health

# **LEGEND**

- MW-8 DESTROYED GROUNDWATER MONITORING WELL LOCATION
- B-2 SOIL BORING LOCATION
- MW9 DESTROYED EXXON MONITORING WELL LOCATION



**FIGURE 2**  
**SITE MAP**  
**ARCO FACILITY NO. 629**  
**13482 BROOKHURST STREET**  
**GARDEN GROVE, CA.**

PROJECT NO. GOB9L	DRAWN BY K. MARTIN	A B C D SM
FILE NO. 5-607-66Q	PREPARED BY S. NIELSEN	
DATE 13 MAR 06	REV. 1	

**Delta**  
Environmental  
Consultants, Inc.